







000001 00000000



Multilayer wiring
lamination wiring

105 → an isotropic conductive
film
conductive paste
or bump



PWB wiring
gateways




Fig. 4A

connecting wires =
current supply line





Fig. 4B

Underlying support members
cathode \Rightarrow common wiring; electrically connected to connecting wires
connecting wires electrically connected to PWB wiring \therefore connecting wires connected to PFC.

COVERING MEMBER
moisture absorbing material
resin

DIRECT



02

Fig. 7

(via hole)
wings

7082

410a

SOURCE DRIVER
CIRCUIT 401

Catharine
P. 28/10/10

431 PIXEL PORTION 403

410c

707b

بِسْمِ اللَّهِ الرَّحْمَنِ الرَّحِيمِ

gs (via hole)

703/5t sealing member

712
Pain (for sealing)

PWB
Training

PC